



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
June 16

### Repair Work

Devil's Slide (post mile 39.14)

- Whaler (bracing) wall construction:  
Whaler wall 'A' (upper level ocean side) – complete.  
Whaler wall 'B' (lower level ocean side) – excavation continued today.



Excavating for wall B

Whaler wall 'C' (lower level cliff side) – complete.  
Whaler wall 'D' (upper level cliff side) – Wall is approximately 70% complete.

- Drilling and tie back installation:  
Whaler wall 'A' – drilling continued using the reach over rig.  
Stressing tie back cables also took place.



Drilling at wall A using the reach over rig.



Stressed cables – wall B

Whaler wall 'C' – drilling continued to-day.



Drilling at wall C